	Туре	L#	Hits	Search Text	DBs	Time Stamp
1	BRS	L11	0	6 not 1	USPAT; EPO; JPO; Derwen	2000/12/04 06:58
2	BRS	L1	42	(sinter sintering) and (cooling adj3 rate) and (magnet magnetic ferromagnetic) and (148/\$.ccls 419/\$.ccls.) and (rare adj3 earth)	USPAT; EPO; JPO; Derwen	2000/12/04 07:03
3	BRS	L16	27	1 not 6	USPAT; EPO; JPO; Derwen	2000/12/04 07:01
4	BRS	L6	15	(sinter sintering) same (cooling adj3 rate) and (magnet magnetic ferromagnetic) and (148/\$.ccls 419/\$.ccls.) and (rare adj3 earth)		2000/12/04 07:02
5	BRS	L26	75	(sinter sintering) and (cooling adj3 rate) and (magnet magnetic ferromagnetic) and (148/\$.ccls 419/\$.ccls.)	USPAT; EPO; JPO; Derwen	2000/12/04 07:06
6	BRS	L21	30	(sinter sintering) same (cooling adj3 rate) and (magnet magnetic ferromagnetic) and (148/\$.ccls 419/\$.ccls.)	USPAT; EPO; JPO; Derwen	2000/12/04 07:04
7	BRS	L31	100	(sinter sintering) same (cooling adj3 rate) and (148/\$.ccls 419/\$.ccls.)	USPAT; EPO; JPO; Derwen	2000/12/04 08:07
8	BRS	L36	250	(sinter sintering) and (cooling adj3 rate) and (148/\$.ccls 419/\$.ccls.)	USPAT; EPO; JPO; Derwen	2000/12/04 07:07
9	BRS	L41	0	31 not 36	USPAT; EPO; JPO; Derwen	2000/12/04 08:07

	Comments	Error Definition	Err ors
1			0
2			0
3			0
4			0
5			0
6			0
7			0
8		 	0
9			0